



Damage Price Guide

| Area | Part or Component | Damage or Condition | SWB | LWB |
|------------------------|----------------------------------|----------------------------------|------|-----|
| Front | Badge | Broken/Damaged/Missing | 49 | 49 |
| | Bonnet | Scratch/Scuff <75mm Paint Damage | 235 | 268 |
| | | Scratch/Scuff - Medium 75-150mm | 575 | 571 |
| | | Scratch/Scuff - Large 150mm+ | 856 | 812 |
| | | Dent - Small 25-75mm | 274 | 307 |
| | | Dent - Medium 75-150mm | 652 | 648 |
| | | Dent - Large 150mm+ | 971 | 928 |
| | Bumper Moulding | Broken/Damaged/Missing | 100 | 110 |
| | Bumper Skirt | Broken/Damaged/Missing/Scuffed | 79 | 95 |
| | Front Bumper | Scratch/Scuff <75mm Paint Damage | 212 | 260 |
| | | Scratch/Scuff - Medium 75-150mm | 289 | 329 |
| | | Scratch/Scuff - Large 150mm+ | 479 | 529 |
| | | Dent - Small 25-75mm | 250 | 298 |
| | | Dent - Medium 75-150mm | 366 | 406 |
| | | Dent - Large 150mm+ | 595 | 645 |
| | Fog Light (Right/Left) | Broken/Damaged/Missing | 80 | 80 |
| | Front Grille | Broken/Damaged/Missing | 117 | 242 |
| | Indicator (Right/Left) | Broken/Damaged/Missing | 58 | 58 |
| | Front Skirt (Right/Left) | Broken/Damaged/Missing | 79 | 95 |
| | Tow Eye Cover | Broken/Damaged/Missing | 25 | 39 |
| Wiper Arm | Broken/Damaged/Missing | 71 | 92 | |
| Wiper Blades | Broken/Damaged/Missing | 28 | 44 | |
| Number Plate | Broken/Damaged/Missing | 25 | 25 | |
| Wind Screen | Glass chip 5-10mm | 55 | 55 | |
| Side | Door (Front/Rear) | Scratch/Scuff <75mm Paint Damage | 291 | 277 |
| | | Scratch/Scuff - Medium 75-150mm | 651 | 587 |
| | | Scratch/Scuff - Large 150mm+ | 949 | 833 |
| | | Dent - Small 25-75mm | 329 | 316 |
| | | Dent - Medium 75-150mm | 728 | 664 |
| | | Dent - Large 150mm+ | 1065 | 948 |
| | Door Handle (Front/Rear) | Broken/Damaged | 47 | 52 |
| | | Scratch/Scuff <75mm Paint Damage | 47 | 52 |
| | Door Seal (Front/Rear) | Broken/Damaged/Missing | 64 | 68 |
| | Front Wing | Scratch/Scuff <75mm Paint Damage | 183 | 199 |
| | | Scratch/Scuff - Medium 75-150mm | 492 | 469 |
| | | Scratch/Scuff - Large 150mm+ | 757 | 699 |
| | | Dent - Small 25-75mm | 221 | 238 |
| | | Dent - Medium 75-150mm | 569 | 546 |
| | | Dent - Large 150mm+ | 872 | 814 |
| | Fuel Flap | Broken/Damaged | 175 | 171 |
| | | Scratch/Scuff <75mm Paint Damage | 129 | 123 |
| | Side Indicator Repeater | Broken/Damaged/Missing | 37 | 37 |
| | Door Mirror Glass | Broken/Damaged/Missing | 35 | 48 |
| | Mirror Housing | Scratch/Scuff <75mm Paint Damage | 65 | 65 |
| Broken/Damaged/Missing | | 151 | 184 | |
| Moulding (Front/Rear) | Broken/Damaged/Missing | 43 | 60 | |
| Rear Wing | Scratch/Scuff <75mm Paint Damage | 394 | 454 | |
| | Scratch/Scuff - Medium 75-150mm | 810 | 837 | |

| Area | Part or Component | Damage or Condition | SWB | LWB |
|--------------------------------|--------------------------------|----------------------------------|------|------|
| Side ... | Rear Wing ... | Scratch/Scuff - Large 150mm+ | 1136 | 1113 |
| | | Dent - Small 25-75mm | 432 | 493 |
| | | Dent - Medium 75-150mm | 887 | 914 |
| | | Dent - Large 150mm+ | 1251 | 1228 |
| Pillar A | Pillar A | Scratch/Scuff <75mm Paint Damage | 185 | 133 |
| | | Scratch/Scuff - Medium 75-150mm | 241 | 157 |
| | | Scratch/Scuff - Large 150mm+ | 250 | 162 |
| | | Dent - Small 25-75mm | 224 | 172 |
| | | Dent - Medium 75-150mm | 318 | 234 |
| | | Dent - Large 150mm+ | 366 | 278 |
| Pillar B | Pillar B | Scratch/Scuff <75mm Paint Damage | 208 | 172 |
| | | Scratch/Scuff - Medium 75-150mm | 291 | 216 |
| | | Scratch/Scuff - Large 150mm+ | 327 | 229 |
| | | Dent - Small 25-75mm | 246 | 211 |
| | | Dent - Medium 75-150mm | 368 | 293 |
| | | Dent - Large 150mm+ | 442 | 345 |
| Pillar C | Pillar C | Scratch/Scuff <75mm Paint Damage | 177 | 177 |
| | | Scratch/Scuff - Medium 75-150mm | 245 | 245 |
| | | Scratch/Scuff - Large 150mm+ | 282 | 282 |
| | | Dent - Small 25-75mm | 216 | 216 |
| | | Dent - Medium 75-150mm | 322 | 322 |
| | | Dent - Large 150mm+ | 397 | 397 |
| Pillar D | Pillar D | Scratch/Scuff <75mm Paint Damage | 150 | 200 |
| | | Scratch/Scuff - Medium 75-150mm | 181 | 282 |
| | | Scratch/Scuff - Large 150mm+ | 190 | 316 |
| | | Dent - Small 25-75mm | 189 | 239 |
| | | Dent - Medium 75-150mm | 258 | 359 |
| | | Dent - Large 150mm+ | 305 | 431 |
| Sill | Sill | Scratch/Scuff <75mm Paint Damage | 168 | 148 |
| | | Scratch/Scuff - Medium 75-150mm | 235 | 171 |
| | | Scratch/Scuff - Large 150mm+ | 256 | 173 |
| | | Dent - Small 25-75mm | 207 | 186 |
| | | Dent - Medium 75-150mm | 312 | 248 |
| | | Dent - Large 150mm+ | 372 | 289 |
| Underside Protection | Underside Protection | Broken/Damaged/Missing | 78 | 87 |
| Wheel Trim (Front/Rear) | Wheel Trim (Front/Rear) | Broken/Damaged/Missing | 32 | 36 |
| WingTrims | WingTrims | Missing | 10 | 36 |
| Wheel Arch (Front/Rear) | Wheel Arch (Front/Rear) | Scratch/Scuff <75mm Paint Damage | 394 | 454 |
| | | Scratch/Scuff - Medium 75-150mm | 810 | 837 |
| | | Scratch/Scuff - Large 150mm+ | 1136 | 1113 |
| | | Dent - Small 25-75mm | 432 | 493 |
| | | Dent - Medium 75-150mm | 887 | 914 |
| | | Dent - Large 150mm+ | 1251 | 1228 |
| Door Glass (Front/Rear) | Door Glass (Front/Rear) | Glass chip 5-10mm | 35 | 35 |
| Alloy/Steel Wheel (Front/Rear) | Alloy/Steel Wheel (Front/Rear) | Scratch/Scuff <75mm Paint Damage | 65 | 65 |
| Left Side Rear Panel | Left Side Rear Panel | Scratch/Scuff <75mm Paint Damage | 394 | 454 |
| | | Scratch/Scuff - Medium 75-150mm | 810 | 837 |
| | | Scratch/Scuff - Large 150mm+ | 1136 | 1113 |

| Area | Part or Component | Damage or Condition | SWB | LWB |
|------------------------------|--------------------------|----------------------------------|------|------|
| Side ... | Left Side Rear Panel ... | Dent - Small 25-75mm | 432 | 493 |
| | | Dent - Medium 75-150mm | 887 | 914 |
| | | Dent - Large 150mm+ | 1251 | 1228 |
| | Right Side Rear Panel | Scratch/Scuff <75mm Paint Damage | 394 | 454 |
| | | Scratch/Scuff - Medium 75-150mm | 810 | 837 |
| | | Scratch/Scuff - Large 150mm+ | 1136 | 1113 |
| | | Dent - Small 25-75mm | 432 | 493 |
| | | Dent - Medium 75-150mm | 887 | 914 |
| | | Dent - Large 150mm+ | 1251 | 1228 |
| | Side Wall | Scratch/Scuff <75mm Paint Damage | - | 527 |
| | | Scratch/Scuff - Medium 75-150mm | - | 1128 |
| | | Scratch/Scuff - Large 150mm+ | - | 1305 |
| | | Dent - Small 25-75mm | - | 566 |
| | | Dent - Medium 75-150mm | - | 1205 |
| | | Dent - Large 150mm+ | - | 1421 |
| | Side Loading Door | Scratch/Scuff <75mm Paint Damage | 417 | 516 |
| | | Scratch/Scuff - Medium 75-150mm | 842 | 946 |
| | | Scratch/Scuff - Large 150mm+ | 1179 | 1221 |
| | | Dent - Small 25-75mm | 392 | 456 |
| | | Dent - Medium 75-150mm | 919 | 1023 |
| | | Dent - Large 150mm+ | 1294 | 1337 |
| Rear | Rear Badge | Broken/Damaged/Missing | 29 | 29 |
| | Boot Lock | Broken/Damaged/Missing | 238 | 120 |
| | Rear Bumper | Scratch/Scuff <75mm Paint Damage | 216 | 189 |
| | | Scratch/Scuff - Medium 75-150mm | 296 | 190 |
| | | Scratch/Scuff - Large 150mm+ | 296 | 190 |
| | | Dent - Small 25-75mm | 255 | 228 |
| | | Dent - Medium 75-150mm | 373 | 267 |
| | | Dent - Large 150mm+ | 412 | 305 |
| | Rear Light (Right/Left) | Broken/Damaged/Missing | 138 | 111 |
| | Rear Number Plate Light | Broken/Damaged/Missing | 34 | 37 |
| | Tow Eye Cover | Broken/Damaged/Missing | 145 | - |
| | Rear Screen | Glass chip 5-10mm | 35 | 35 |
| | Number Plate | Broken/Damaged/Missing | 25 | 25 |
| | Rear Loading Door | Scratch/Scuff <75mm Paint Damage | 284 | 345 |
| | | Scratch/Scuff - Medium 75-150mm | 404 | 481 |
| Scratch/Scuff - Large 150mm+ | | 463 | 519 | |
| Dent - Small 25-75mm | | 322 | 383 | |
| Dent - Medium 75-150mm | | 481 | 558 | |
| Dent - Large 150mm+ | | 579 | 634 | |
| Step | Broken/Damaged/Missing | 350 | 350 | |
| Tail-lift | Broken/Damaged/Missing | 950 | 950 | |
| Roof | Aerial | Broken/Damaged/Missing | 77 | 78 |
| | Roof | Scratch/Scuff <75mm Paint Damage | 668 | 464 |
| | | Scratch/Scuff - Medium 75-150mm | 980 | 647 |
| | | Scratch/Scuff - Large 150mm+ | 1166 | 693 |
| | | Dent - Small 25-75mm | 707 | 503 |
| | | Dent - Medium 75-150mm | 1057 | 724 |
| | | Dent - Large 150mm+ | 1281 | 809 |

| Area | Part or Component | Damage or Condition | SWB | LWB |
|------------------------|-----------------------------|----------------------------------|-----|-----|
| Interior | Bulkhead | Broken/Damaged/Missing | 402 | 402 |
| | Centre Console | Broken/Damaged/Missing | 80 | 85 |
| | | Burn/Holed/Cut | 80 | 85 |
| | Door Panel | Burn/Holed/Cut | 125 | 125 |
| | | Missing | 234 | 184 |
| | Front Left Seat Back Cover | Broken/Damaged/Missing | 190 | 129 |
| | | Burn/Holed/Cut | 125 | 125 |
| | Front Left Seat Base Cover | Broken/Damaged/Missing | 120 | 131 |
| | | Burn/Holed/Cut | 120 | 125 |
| | Front Right Seat Back Cover | Broken/Damaged/Missing | 116 | 141 |
| | | Burn/Holed/Cut | 116 | 125 |
| | Front Right Seat Base Cover | Broken/Damaged/Missing | 136 | 127 |
| | | Burn/Holed/Cut | 125 | 125 |
| | Gear Lever Gaiter | Broken/Damaged/Missing | 46 | 58 |
| | | Burn/Holed/Cut | 46 | 58 |
| | Glove Compartment | Broken/Damaged/Missing | 89 | 142 |
| | Head Restraint | Broken/Damaged/Missing | 151 | 151 |
| | Interior Carpet | Burn/Holed/Cut | 125 | 125 |
| | | Missing | 717 | 612 |
| | Interior Lighting | Broken/Damaged/Missing | 57 | 66 |
| | Key | Broken/Damaged/Missing | 267 | 350 |
| | Rear View Mirror | Broken/Damaged/Missing | 464 | 79 |
| | Rear Armrest | Broken/Damaged/Missing | 179 | 179 |
| | Rear Left Seat Back Cover | Broken/Damaged/Missing | 120 | 234 |
| | | Burn/Holed/Cut | 120 | 125 |
| | Rear Left Seat Base Cover | Broken/Damaged/Missing | 532 | 532 |
| | | Burn/Holed/Cut | 125 | 125 |
| | Rear Right Seat Back Cover | Broken/Damaged/Missing | 290 | 290 |
| | | Burn/Holed/Cut | 125 | 125 |
| | Rear Right Seat Base Cover | Broken/Damaged/Missing | 440 | 440 |
| Burn/Holed/Cut | | 125 | 125 | |
| Roof Lining | Broken/Damaged/Missing | 125 | 125 | |
| | Burn/Holed/Cut | 125 | 125 | |
| Speaker | Broken/Damaged/Missing | 43 | 43 | |
| Sun Visor | Broken/Damaged/Missing | 68 | 68 | |
| | Burn/Holed/Cut | 68 | 68 | |
| Window Handle | Broken/Damaged/Missing | 21 | 20 | |
| Locking Wheel Bolt Key | Broken/Damaged/Missing | 160 | 160 | |
| Ply Lining | Broken/Damaged/Missing | 155 | 155 | |
| Accessories | Tool Kit | Missing | 50 | 67 |
| | Hub Covers | Missing | 19 | 30 |
| | | Scratch/Scuff <75mm Paint Damage | 30 | 30 |
| | Decals (Single) | Broken/Damaged/Missing | 63 | 63 |
| | Decals (Full Set) | Broken/Damaged/Missing | 221 | 221 |